

ALPHANUMERIC INDEX — CROSS-REFERENCE (Continued)

Industry Part Number	Motorola Direct Replacement	Motorola Similar Replacement	Page Number	Industry Part Number	Motorola Direct Replacement	Motorola Similar Replacement	Page Number
2SB648		MJE350	3-880	2SC1005		BU207	3-343
2SB649		MJE350	3-880	2SC1013		MJE180	3-862
2SB653		MJ15016	3-9	2SC1014		MJE181	3-862
2SB654		MJ15016	3-9	2SC1025		2N3584	3-20
2SB655		MJ15002	3-710	2SC1030		2N5760	3-116
2SB656		MJ15002	3-710	2SC1031		2N3585	3-20
2SB668		TIP32A	3-1073	2SC1034		MJ12003	3-642
2SB669		TIP32B	3-1073	2SC1036		BU207	3-343
2SB673		2N6042	3-139	2SC1050		MJ411	3-522
2SB674		2N6041	3-139	2SC1051		2N5760	3-116
2SB675		2N6040	3-139	2SC1055		2N5430	3-101
2SB676		TIP127	3-1098	2SC1059		2N3739	3-37
2SB677		TIP125	3-1098	2SC1060		TIP31A	3-1073
2SB679		TIP117	3-1095	2SC1061		TIP31A	3-1073
2SB681		MJ15002	3-710	2SC1078		MJ12003	3-642
2SB686		TIP42C	3-1083	2SC1079		MJ15001	3-710
2SB688		MJE15029	3-972	2SC1080		MJ15001	3-710
2SB689		TIP42C	3-1083	2SC1086		BU207	3-343
2SB690		TIP42C	3-1083	2SC1088		MJE3439	3-908
2SB691		MJE4352	3-910	2SC1089		MJE3439	3-908
2SB692		MJE4352	3-910	2SC1096		MJE180	3-862
2SB693		2N6287	3-172	2SC1098		2N4923	3-79
2SB694		MJ11015	3-629	2SC1099		BU207	3-343
2SB695		MJE4352	3-910	2SC1100		BU207	3-343
2SB696		MJ15002	3-710	2SC1101		MJ12003	3-642
2SB697		MJ15002	3-710	2SC1102		2N3739	3-37
2SB707		2N6107	3-151	2SC1104		2N3585	3-20
2SB708		2N6107	3-151	2SC1105		2N3739	3-37
2SB711		2N6041	3-139	2SC1106		2N6308	3-181
2SB712		2N6042	3-139	2SC1107		2N6123	3-154
2SB713		MJE4352	3-910	2SC1108		2N6123	3-154
2SB717		MJE350	3-880	2SC1109		2N6123	3-154
2SB718		MJE350	3-880	2SC1110		2N6123	3-154
2SB719		MJE15031	3-972	2SC1111		MJ15001	3-710
2SB720		MJE15031	3-972	2SC1112		MJ15001	3-710
2SB722		MJ15002	3-710	2SC1113		MJE15030	3-972
2SB723		MJ15023	3-723	2SC1114		2N6543	3-215
2SB724		TIP32A	3-1073	2SC1115		MJ15001	3-710
2SB727		MJE15029	3-972	2SC1116		MJ15011	3-716
2SB743		MJE170	3-862	2SC1124		MPS-U04	3-1044
2SB744		MJE172	3-862	2SC1125		MPS-U10	3-1052
2SB750		TIP115	3-1095	2SC1130		2N6543	3-215
2SB751		TIP126	3-1098	2SC1131		2N6543	3-215
2SB753		TIP42C	3-1083	2SC1132		BU207	3-343
2SB754		2N6109	3-151	2SC1140		2N6547	3-225
2SB772		MJE170	3-862	2SC1141		2N6546	3-225
2SB840L		MJD5731-1	—	2SC1142		MJ13015	3-670
2SB840S		MJD5731	—	2SC1143		MJ13014	3-670
2SB841L		MJD5731-1	—	2SC1151		MJ12003	3-642
2SB841S		MJD5731	—	2SC1152		2N6308	3-181
2SB905		MJD5731-1	—	2SC1153		MJ12003	3-642
2SB906		MJD32C1	3-797	2SC1154		MJ12003	3-642
2SB907		MJD6036-1	3-848	2SC1155		MJE182	3-862
2SB908		MJD6036-1	3-848	2SC1156		2N6543	3-215
2SB962		MJD45H11-1	3-808	2SC1157		2N4923	3-79
2SB963		MJD117-1	3-816	2SC1160		2N3738	3-37
2SB967		MJD210	3-832	2SC1161		2N3738	3-37
2SB968		MJD210	3-832	2SC1162		MJE180	3-862
2SC1004		MJ12003	3-642	2SC1167		MJ12003	3-642
2SC1004A		MJ12003	3-642	2SC1168		2N3739	3-37

\*Consult Motorola if a direct replacement is necessary.