

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
TMPP5461 (Cont'd) DE326 3 DGE THJ5461 3 SPR	TMPP5950 2N5950 2 2N5486 3 INL	TMPPFB244C (Cont'd) THJBF244C 3 SPR	TMPPF305 J305 2 2N5484 3 INL	TMPT1009F4 MMBC1009F4 1 MOTA	TMPT2907A (Cont'd) BSS82B 3 SIEG
TMPP5462 2N5462 2 DE326 3 DGE THJ5462 3 SPR	2N5486 3 MOTA 2N5950-18 3 NSC PN4416 3 SIX THJ5950 3 SPR	TMPPFB246A BF246A 2 2N5639 3 INL THJBF246A 3 SPR	TMPPF308 J308 2 THJJ308 3 SPR TPJ308 3 SPR	TMPT1009F5 MMBC1009F5 1 MOTA	MMBT2407 3 MOTA PN2907A 3 NSC THC2907A 3 SPR TP2907A 3 SPR
TMPP5484 2N5484 2 2N5246 3 IFC DE180 3 DGE THJ5484 3 SPR	TP5950 3 SPR TMPP5951 2N5951 2 2N5486 3 INL	TMPPFB246B BF246B 2 2N5638 3 INL THJBF246B 3 SPR	TMPPF309 J309 2 THJJ309 3 SPR TPJ309 3 SPR	TMPT1621B3 MMBC1621B3 1 MOTA	TMPT1621B4 MMBC1621B4 1 MOTA
TMPP5485 2N5485 2 2N5245 3 IFC DE451 3 DGE THJ5485 3 SPR	2N5640 3 MOTA 2N5951-18 3 NSC PN4416 3 SIX THJ5951 3 SPR	TMPPFB246C BF246C 2 2N5638 3 INL THJBF246C 3 SPR	TMPPF310 J310 2 THJJ310 3 SPR TPJ310 3 SPR	TMPT1622D6 MMBC1622D6 1 MOTA	TMPT1622D7 MMBC1622D7 1 MOTA
TMPP5486 2N5486 2 2N5247 3 IFC THJ5486 3 SPR	TIS59 3 TII TP5951 3 SPR TMPP5952 2N5952 2 2N5484 3 INL	TMPPFB256A BF256A 2 2N5484 3 INL THJBF256A 3 SPR	TMPPF310 J310 2 THJJ310 3 SPR TPJ310 3 SPR	TMPT1622D8 MMBC1622D8 1 MOTA	TMPT1623L3 MMBC1623L3 1 MOTA
TMPP5555 2N5555 2 2N5949 3 IFC J310 3 INL THJ5555 3 SPR	2N5640 3 MOTA 2N5952-18 3 NSC J305 3 SIX THJ5952 3 SPR	TMPPFB256B BF256B 2 2N4416 3 INL THJBF256B 3 SPR	TMPPF1086 P1086 2 2N5461 3 MOTA THJP1086 3 SPR	TMPT1623L4 MMBC1623L4 1 MOTA	TMPT1623L5 MMBC1623L5 1 MOTA
TMPP5556 2N5556 2 2N3685 3 INL 2N3821 3 IFC THJ5556 3 SPR TP5556 3 SPR	2N5484 3 INL 2N5640 3 MOTA 2N5952-18 3 NSC J305 3 SIX THJ5952 3 SPR	TMPPFB256C BF256C 2 2N4416 3 INL THJBF256C 3 SPR	TMPPF305 THJU304 3 SPR TPU304 3 SPR	TMPT1623L6 MMBC1623L6 1 MOTA	TMPT1623L7 MMBC1623L7 1 MOTA
TMPP5557 2N5557 2 2N3684 3 INL 2N3611 3 IFC THJ5557 3 SPR TP5557 3 SPR	TIS58 3 TII TP5952 3 SPR TMPP5953 2N5953 2 2N5484 3 INL	TMPPFB256D BF256D 2 2N4416 3 INL THJBF256D 3 SPR	TMPPF306 THJU305 3 SPR TPU305 3 SPR	TMPT1623L8 MMBC1623L8 1 MOTA	TMPT1623L9 MMBC1623L9 1 MOTA
TMPP5558 2N5558 2 2N3684 3 INL 2N5362 3 IFC THJ5558 3 SPR TP5558 3 SPR	2N5640 3 MOTA 2N5952-18 3 NSC J305 3 SIX SX3819 3 TII THJ5953 3 SPR	TMPPF112 J112 2 THJJ112 3 SPR	TMPPF306 U306 2 2N3993 3 MOTA THJU306 3 SPR TPU306 3 SPR	TMPT1624N5 MMBC1624N5 1 MOTA	TMPT1624N6 MMBC1624N6 1 MOTA
TMPP5559 2N5559 2 BSV78 3 PHIN THJ5638 3 SPR TIS73 3 IFC	TIS58 3 TII TP5953 3 SPR TMPP6451 2N6451 2 2N4393 3 MOTA	TMPPF112A J112A 2 2N5459 3 MOTA J112 3 INL PN4092 3 NSC THJJ112A 3 SPR	TMPPF308 THJU308 3 SPR TPU308 3 SPR	TMPT1624N7 MMBC1624N7 1 MOTA	TMPT2221 BSS81B 3 SIEG DE123A 3 DGE GES222A 3 GESY
TMPP5638 2N5638 2 BSV78 3 PHIN THJ5639 3 SPR TIS74 3 IFC	2N5484 3 INL 2N5640 3 MOTA 2N5952-18 3 NSC J305 3 SIX SX3819 3 TII THJ5953 3 SPR	TMPPF112B J112B 2 2N5459 3 MOTA J112 3 INL PN4092 3 NSC THJJ112B 3 SPR	TMPPF308 U308 2 THJU308 3 SPR TPU308 3 SPR	TMPT2221A BSS79B 3 SIEG GES2221A 3 GESY THC2221A 3 SPR TP2221A 3 SPR	TMPT2222 BSS81C 3 SIEG GES2222 3 GESY PN2222 3 NSC THC2222 3 SPR TP2222 3 SPR
TMPP5640 2N5640 2 BSV80 3 PHIN THJ5640 3 SPR TIS75 3 IFC	2N5484 3 INL 2N5640 3 MOTA 2N5952-18 3 NSC J305 3 SIX SX3819 3 TII THJ5953 3 SPR	TMPPF113 J113 2 THJJ113 3 SPR	TMPPF309 U309 2 THJU309 3 SPR TPU309 3 SPR	TMPT2222A BSS79C 3 SIEG DE102A 3 DGE DE123A 3 DGE GES2222A 3 GESY	TMPT2222B MMBT2222A 3 NSC PN2222A 3 NSC THC2222A 3 SPR TP2222A 3 SPR
TMPP5653 2N5653 2 BSV78 3 PHIN THJ5653 3 SPR TIS74 3 IFC	2N5484 3 INL 2N5640 3 MOTA 2N5952-18 3 NSC J305 3 SIX SX3819 3 TII THJ5953 3 SPR	TMPPF113A J113A 2 2N5458 3 MOTA J113 3 INL PN4093 3 NSC THJJ113A 3 SPR	TMPPF309 U309 2 THJU309 3 SPR TPU309 3 SPR	TMPT2222C MMBT2222A 3 NSC PN2222A 3 NSC THC2222A 3 SPR TP2222A 3 SPR	TMPT2222D MMBT2222A 3 NSC PN2222A 3 NSC THC2222A 3 SPR TP2222A 3 SPR
TMPP5654 2N5654 2 BSV79 3 PHIN THJ5654 3 SPR TIS75 3 IFC	2N5484 3 INL 2N5640 3 MOTA 2N5952-18 3 NSC J305 3 SIX SX3819 3 TII THJ5953 3 SPR	TMPPF113B J113B 2 2N5458 3 MOTA J113 3 INL PN4093 3 NSC THJJ113B 3 SPR	TMPPF309 U309 2 THJU309 3 SPR TPU309 3 SPR	TMPT2222E MMBT2222A 3 NSC PN2222A 3 NSC THC2222A 3 SPR TP2222A 3 SPR	TMPT2222F MMBT2222A 3 NSC PN2222A 3 NSC THC2222A 3 SPR TP2222A 3 SPR
TMPP5668 2N5668 2 2N5484 3 INL 2N5953 3 IFC BF245A 3 PHIN DE457 3 DGE THJ5668 3 SPR TP5668 3 SPR	2N5484 3 INL 2N5640 3 MOTA 2N5952-18 3 NSC J305 3 SIX SX3819 3 TII THJ5953 3 SPR	TMPPF114 J114 2 2N5459 3 MOTA J112 3 INL PN4092 3 NSC THJJ114 3 SPR	TMPPF309 U309 2 THJU309 3 SPR TPU309 3 SPR	TMPT2222G MMBT2222A 3 NSC PN2222A 3 NSC THC2222A 3 SPR TP2222A 3 SPR	TMPT2222H MMBT2222A 3 NSC PN2222A 3 NSC THC2222A 3 SPR TP2222A 3 SPR
TMPP5669 2N5669 2 2N5485 3 INL 2N5952 3 IFC BF245B 3 PHIN THJ5669 3 SPR TP5669 3 SPR	2N5484 3 INL 2N5640 3 MOTA 2N5952-18 3 NSC J305 3 SIX SX3819 3 TII THJ5953 3 SPR	TMPPF114A J114A 2 2N5459 3 MOTA J112 3 INL PN4092 3 NSC THJJ114A 3 SPR	TMPPF309 U309 2 THJU309 3 SPR TPU309 3 SPR	TMPT2222I MMBT2222A 3 NSC PN2222A 3 NSC THC2222A 3 SPR TP2222A 3 SPR	TMPT2222J MMBT2222A 3 NSC PN2222A 3 NSC THC2222A 3 SPR TP2222A 3 SPR
TMPP5670 2N5670 2 2N5486 3 INL 2N5950 3 IFC BF245C 3 PHIN THJ5670 3 SPR TP5670 3 SPR	2N5484 3 INL 2N5640 3 MOTA 2N5952-18 3 NSC J305 3 SIX SX3819 3 TII THJ5953 3 SPR	TMPPF114B J114B 2 2N5459 3 MOTA J112 3 INL PN4092 3 NSC THJJ114B 3 SPR	TMPPF309 U309 2 THJU309 3 SPR TPU309 3 SPR	TMPT2222K MMBT2222A 3 NSC PN2222A 3 NSC THC2222A 3 SPR TP2222A 3 SPR	TMPT2222L MMBT2222A 3 NSC PN2222A 3 NSC THC2222A 3 SPR TP2222A 3 SPR
TMPP5949 2N5949 2 2N5486 3 INL 2N5638 3 MOTA 2N5949-18 3 NSC PN4416 3 SIX SX3819 3 TII THJ5949 3 SPR TIS59 3 TII TP5949 3 SPR	2N5484 3 INL 2N5640 3 MOTA 2N5952-18 3 NSC J305 3 SIX SX3819 3 TII THJ5953 3 SPR	TMPPF114C J114C 2 2N5459 3 MOTA J112 3 INL PN4092 3 NSC THJJ114C 3 SPR	TMPPF309 U309 2 THJU309 3 SPR TPU309 3 SPR	TMPT2222M MMBT2222A 3 NSC PN2222A 3 NSC THC2222A 3 SPR TP2222A 3 SPR	TMPT2222N MMBT2222A 3 NSC PN2222A 3 NSC THC2222A 3 SPR TP2222A 3 SPR