

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
2N2904 (Cont'd)	2N2905A (Cont'd)	2N2907A (Cont'd)	2N2920 (Cont'd)	2N2952	2N2977 (Cont'd)
2N2905 3 PHIN	TMPT3798 3 SPR	BSR16 3 APX	MP312-78 1 MPS	2N1711 1 MOTA	MP312 3 MPS
2N2906A 3 PHIN	TP3798 3 SPR	BSS80C 3 SIEG	IT120 3 INL	D40D7 1 GESY	2N2978
2N2907 3 MOTA	TP5189 3 SPR	DE129 3 DGE	IT121 3 INL	DE123A 1 DGE	2N2919 1 MOTA
2N4036 3 RCA	2N2906	DE159 3 DGE	IT122 3 INL	D40D5 3 GESY	DE81 1 DGE
2N4037 3 RCA	DE159 1 DGE	GES2907A 3 GESY	MP310-78 3 MPS	DE128 3 DGE	IT120 1 INL
40319 3 RCA	GES2906 1 GESY	IT131 3 INL	2N2920A	PN2222A 3 NSC	MD2219 3 MOTA
40406 3 RCA	PN2906 1 NSC	MMBT2907A 3 MOTA	2N2920 1 INL	THC1711 3 SPR	MP312 3 MPS
D41D1 3 GESY	THC2906 1 SPR	MPS8598 3 MOTA	MP312-78 1 MPS	2N2953	MP312-78 3 MPS
D41D8 3 GESY	TMPT2906 1 SPR	PMBT2907A 3 APX	DE81 3 DGE	2N1194 1 LTE	2N2979
DE159 3 DGE	TP2906 1 SPR	PN200 3 NSC	MOTA	DE102A 1 DGE	2N2920 1 MOTA
MPS3638 3 GESY	2N2904A 3 SGTI	THC3905 3 SPR	DE199 1 DGE	2N2954	DE81 1 DGE
MPSH54 3 MOTA	2N2906A 3 SGTI	THC3906 3 SPR	2N2922	2N834 1 MOTA	IT120 1 INL
PN2906 3 NSC	2N2907A 3 PHIN	THC3962 3 SPR	DE199 1 DGE	BCY56 3 PHIN	MP312 3 MPS
PN3638-5 3 NSC	BC297 3 SGTI	TMP3905 3 SPR	2N2923	BSX20 3 SGTI	MP312-78 3 MPS
THC3638 3 SPR	BC327 3 PHIN	TMPT3906 3 SPR	DE199 1 DGE	MPS834 3 NSC	2N2980
TMPT3638 3 SPR	BCY71 3 PHIN	THC2908 1 SPR	THC2923 1 SPR	2N2955	2N2060 1 MOTA
TP3638 3 SPR	BS2906 3 SGTI	2N2908	DE199 1 DGE	DE126A 1 DGE	DE81 1 DGE
2N2904A	BS2906A 3 SGTI	2N2909	THC2924 1 SPR	GES2955 1 GESY	IT121 1 INL
THC2904A 1 SPR	BSS80B 3 SIEG	2N2221A 1 MOTA	2N2924	2N2956	IT120 3 INL
TP2904A 1 SPR	BSX21 3 PHIN	BSS79B 3 SIEG	DE199 1 DGE	DE126A 1 DGE	MP311 3 MPS
2N2904 3 MOTA	D41D4 3 GESY	GES2221A 3 GESY	2N2925	2N2957	2N2981
2N2905A 3 PHIN	DE128 3 DGE	THC2221A 3 SPR	THC2925 1 SPR	DE126A 1 DGE	2N2060 1 MOTA
2N2906 3 PHIN	DE129 3 DGE	TMPT2221A 3 SPR	2N2926	2N2958	DE81 1 DGE
2N4036 3 RCA	PN200 3 NSC	TP2221A 3 SPR	BC548B 1 PHIN	2N697 1 RCA	IT122 1 INL
D41D1 3 GESY	THC3905 3 SPR	2N2910	DE199 1 DGE	2N2219 1 MOTA	IT120 3 INL
DE129 3 DGE	THC4384 3 SPR	IT122 1 INL	THC2926 1 SPR	DE123A 1 DGE	MP310 3 MPS
2N2905	THC4386 3 SPR	MD2219 1 MOTA	BCW32 3 PHIN	MPS2221 1 GESY	2N2982
DE129 1 DGE	THC4402 3 SPR	IT129 3 INL	BCW60B 3 PHIN	2N1613 3 SGTI	2N2060 1 MOTA
THC2905 1 SPR	TMPT3905 3 SPR	MP310 3 MPS	BCW60C 3 PHIN	2N1711 3 PHIN	IT122 1 INL
TN2905 1 NSC	TMPT4402 3 SPR	2N2911	THC548B 3 SPR	2N4400 3 NSC	IT120 3 INL
TP2905 1 SPR	TP4384 3 SPR	2N5682 1 MOTA	2N2927	D40D7 3 GESY	MP310 3 MPS
2N2904 3 PHIN	TP4386 3 SPR	D44T2 3 GESY	2N2904 1 MOTA	DE126 3 DGE	2N2984
SGSI	2N2906A	DE128 3 DGE	2N2904A 1 SGTI	GES2219 3 GESY	2N5682 1 MOTA
2N2905A 3 PHIN	PN2906A 1 NSC	2N2913	D41D1 1 GESY	THC697 3 SPR	DE128 1 DGE
2N3546 3 MOTA	THC2906A 1 SPR	IT122 1 INL	DE129 1 DGE	THC2219 3 SPR	2N2985
2N3905 3 GESY	TMPT2906A 1 SPR	MP311-78 1 MPS	THC2904 3 SPR	TN2219 3 NSC	DE128 1 DGE
NSC	TPQ2906A 1 SPR	DE81 3 DGE	THC2904A 3 SPR	TP2219 3 SPR	2N2987
2N3906 3 NSC	2N2904 3 SGTI	MP310 3 MPS	TN2904 3 NSC	2N2959	2N4238 1 MOTA
2N4036 3 RCA	2N2906 3 PHIN	2N2914	TP2904 3 SPR	2N2219A 1 SGTI	2N3114 3 MOTA
2N4037 3 RCA	2N2907 3 SGTI	IT120 1 INL	TP2904A 3 SPR	DE123A 1 DGE	2N3500 3 MOTA
BC327 3 PHIN	2N3468 3 MOTA	MP311-78 1 MPS	2N2929	MPS2222 1 GESY	2N5785 3 RCA
D41D4 3 GESY	40319 3 RCA	DE81 3 DGE	DE126A 1 DGE	GES2219A 3 GESY	BC300 3 SGTI
DE159 3 DGE	D41E5 3 GESY	IT122 3 INL	2N2934	THC2219A 3 SPR	BD131 3 PHIN
GES3250 3 GESY	DE129 3 DGE	MP312 3 MPS	2N918 1 THCS	TN2219A 3 NSC	BFY50 3 PHIN
GES3251 3 GESY	DE159 3 DGE	2N2915	BF799 3 SIEG	TP2219A 3 SPR	BSW66 3 PHIN
GES3644 3 GESY	GES2906A 3 GESY	DE81 1 DGE	DE161 3 DGE	2N2970	D40D7 3 GESY
GES4122 3 GESY	MPSA05 3 GESY	IT120 1 INL	PN918 3 NSC	2N3250 1 MOTA	D42T1 3 GESY
MPS3638 3 GESY	MPSA55 3 MOTA	MP311-78 1 MPS	THC918 3 SPR	2N2905 3 PHIN	D44C8 3 GESY
MPS3703 3 NSC	THC3073 3 SPR	MP312 3 MPS	TMP2918 3 SPR	2N3905 3 NSC	D44C9 3 GESY
PN3638-5 3 NSC	THC3121 3 SPR	2N2915A	TP918 3 SPR	DE159 3 DGE	DE128 3 DGE
PN3644-5 3 NSC	THC3963 3 SPR	2N2915 1 MOTA	2N2936	GES3250 3 GESY	DE154 3 DGE
PN3645 3 NSC	2N2907	IT120 1 INL	IT120 1 INL	THC3250 3 SPR	2N2988
PN4122-18 3 NSC	BSS80C 1 SIEG	DE81 3 DGE	MP312 3 MPS	TP3250 3 SPR	2N5681 1 MOTA
PN4916-18 3 NSC	DE159 1 DGE	MP311-78 3 MPS	2N2937	2N2971	D44T2 3 GESY
PN5142-18 3 NSC	GES2907 1 GESY	MP312 3 MPS	IT120 1 INL	2N3250 1 MOTA	DE128 3 DGE
RCA1A05 3 RCA	PN2907 1 NSC	2N2916	MP312 3 MPS	DE81 1 DGE	2N2989
THC3133 3 SPR	THC2907 1 SPR	IT120 1 INL	2N2939	2N2905 3 PHIN	2N5681 1 MOTA
THC3134 3 SPR	TMPT2907 1 SPR	MP311-78 1 MPS	D40D8 1 GESY	2N3905 3 NSC	D40D7 3 GESY
THC3250 3 SPR	TP2907 1 SPR	DE81 3 DGE	2N2941	DE159 3 DGE	D44T2 3 DGE
THC3251 3 SPR	2N2222 3 PHIN	IT122 3 INL	D44T1 1 GESY	GES3250 3 GESY	DE128 3 DGE
THC3502 3 SPR	2N2904 3 PHIN	MD2219 3 MOTA	2N2942	THC3250 3 SPR	THC2017 3 SPR
THC3638 3 SPR	2N2906A 3 PHIN	MP312 3 MPS	DE126A 1 DGE	TP3250 3 SPR	2N2990
THC3644 3 SPR	2N2907A 3 PHIN	2N2916A	2N2943	2N2972	2N5682 1 MOTA
THC4122 3 SPR	SGSI	2N2916 1 MOTA	DE126A 1 DGE	2N2913 1 MOTA	D44T2 3 GESY
THC4916 3 SPR	2N4403 3 MOTA	IT120 1 INL	2N2944	DE81 1 DGE	DE128 3 DGE
THC5142 3 SPR	BC327 3 PHIN	MD2219 1 MOTA	DE159 1 DGE	IT122 1 INL	2N2991
TMPT3638 3 SPR	BCX71G 3 SIEG	IT129 3 INL	THC2944 1 SPR	MP310 3 MPS	2N3420 1 GSE
TP3250 3 SPR	BCY71 3 PHIN	MP311-78 3 MPS	TP2944 1 SPR	MP311-78 3 MPS	2N4307 3 TRWS
TP3251 3 SPR	BCY72 3 PHIN	2N2917	2N2945	2N2973	2N5336 3 MOTA
TP3638 3 SPR	BSR15 3 APX	DE81 1 DGE	DE159 1 DGE	2N2914 1 MOTA	D42C8 3 GESY
TP3644 3 SPR	D41D4 3 GESY	IT122 1 INL	THC2945 1 SPR	DE81 1 DGE	2N2992
2N2905A	MMBT2907 3 MOTA	MD2219 1 MOTA	TP2945 1 SPR	IT122 1 INL	2N3767 1 GSE
THC2905A 1 SPR	MMBT3906 3 MOTA	MP311-78 1 MPS	2N2946	IT120 3 INL	2N6372 3 RCA
TN2905A 1 NSC	MMBT4126 3 MOTA	IT120 3 INL	DE159 1 DGE	MP310 3 MPS	BD139 3 PHIN
TP2905A 1 SPR	MMBT4403 3 MOTA	IT129 3 INL	THC2946 1 SPR	MP311-78 3 MPS	D44C11 3 GESY
2N2904A 3 PHIN	PMBT2907 3 APX	MP310 3 MPS	TP2946 1 SPR	2N2974	DE175 3 DGE
SGSI	PN200 3 NSC	2N2918	2N2947	2N2915 1 MOTA	2N2993
2N2905 3 MOTA	PN3645 3 NSC	DE81 1 DGE	2N5641 1 MOTA	DE81 1 DGE	2N3420 1 GSE
SGSI	THC2696 3 SPR	IT122 1 INL	D44C7 1 GESY	IT120 1 INL	2N4307 3 TRWS
2N3071 3 NSC	THC3136 3 SPR	MD2219 1 MOTA	DE162 1 DGE	MP311-78 3 MPS	2N5336 3 MOTA
SIX	THC3906 3 SPR	MP311-78 1 MPS	MRF485 1 MOTA	MP312 3 MPS	D42C8 3 GESY
2N3459 3 IFC	THC4403 3 SPR	IT120 3 INL	2N6292 3 RCA	2N2975	2N2994
2N3821 3 MOTA	THC4903 3 SPR	IT129 3 INL	BD239A 3 RCA	2N2916 1 MOTA	2N3767 1 GSE
2N4036 3 RCA	TMPT3906 3 SPR	MP310 3 MPS	BU407 3 APX	DE81 1 DGE	2N6372 3 RCA
2N4339 3 INL	TMPT4403 3 SPR	2N2919	DE357 3 DGE	IT120 1 INL	BD139 3 PHIN
SIX	2N2907A	DE81 1 DGE	ST44C7 3 STI	MP311-78 3 MPS	D44C11 3 GESY
BFW12 3 PHIN	BSS82C 1 SIEG	IT120 1 INL	2N2948	MP312 3 MPS	DE175 3 DGE
BFX48 3 SGTI	PN2907A 1 SPR	MD2219 1 MOTA	D44C4 1 GESY	2N2976	2N3009
D41D8 3 GESY	THC2907A 1 SPR	MP312-78 1 MPS	DE162 1 DGE	2N2917 1 MOTA	2N3013 1 SGTI
D42C6 3 GESY	TMPT2907A 1 SPR	IT122 3 INL	2N6290 3 RCA	DE81 1 DGE	DE123A 1 DGE
DE128 3 DGE	TP2907A 1 SPR	IT129 3 INL	BD239 3 RCA	IT120 1 INL	PN3646 1 NSC
DE129 3 DGE	2N2222 3 PHIN	BU407 3 APX	ST44C4 3 STI	IT122 3 INL	THC3009 1 SPR
DE159 3 DGE	2N2906 3 SGTI	ST44C4 3 STI	2N2949	MD2219 3 MOTA	PN100 3 NSC
GES6017 3 GESY	2N2907 3 PHIN	2N2919A	D40D7 1 GESY	MP311-78 3 MPS	THC3013 3 SPR
PN3645-5 3 NSC	SGSI	2N2919 1 MOTA	DE128 1 DGE	MP312 3 MPS	2N3010
PN4143-18 3 NSC	2N4403 3 MOTA	IT120 1 INL	2N2950	2N2977	2N4125 1 GESY
RCA1A0A 3 RCA	2N5086 3 NSC	DE81 3 DGE	D40D7 1 GESY	2N2918 1 MOTA	DE108 1 DGE
THC3503 3 SPR	BC177 3 SGTI	MD2219 3 MOTA	2N2951	DE81 1 DGE	BC558 3 PHIN
THC3798 3 SPR	BC477 3 SGTI	MP312 3 MPS	D40D7 1 GESY	IT120 1 INL	BSS80B 3 SIEG
THC4143 3 SPR	BCX71G 3 SIEG	MP312-78 3 MPS	D40D7 1 GESY	IT122 3 INL	DE159 3 DGE
THC5189 3 SPR	BFX37 3 SGTI	2N2920	DE128 1 DGE	MD2219 3 MOTA	PN200 3 NSC
	BFY50 3 PHIN	DE81 1 DGE		MP311-78 3 MPS	THC4125 3 SPR